



**Wide-Angle Damage Photo**



**Close-Up Damage Photo**







**Front Driver's Side Damage Photo**





**Front Passenger Damage Photo**



**Rear Driver Side Damage Photo**







**Rear Passenger Side Damage Photo**



# VIN Damage Photo

**NOTE:** The VIN Bar Code is Most Often Found Inside the Driver's Door (on pillar).

MFD BY FUJI HEAVY INDUSTRIES LTD.  
MFD IN 10/15

GVWR/PNBV: 4480LB (2032KG)

GAWR/PNBE:FRONT- 2310 LB (1048KG) WITH P225/60R17 98H TIRES,  
17X7J RIMS AT 210 KPA (30 PSI) COLD

GAWR/PNBE:REAR - 2410 LB (1093KG) WITH P225/60R17 98H TIRES,  
17X7J RIMS AT 200 KPA (29 PSI) COLD

THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR  
VEHICLE SAFETY AND THEFT PREVENTION STANDARDS IN EFFECT ON  
THE DATE OF MANUFACTURE SHOWN ABOVE.

VIN: JF2SJARCOGH472236



TYPE:MPV/VTUM

ICES/NMB-002



# Mileage Damage Photo







License Damage Photo